

FEATURE ARTICLES ON—BRAKES • TUNE-UP • TRANSMISSION



MECHANICAL FEATURES

STEERING AND SUSPENSION

	Page
Sell Shock Absorber Service	April 55
Servicing the Nash Rambler Front End	Sept. 44
New Life for Dead Shocks	Oct. 52
Spring Suspension Service	Nov. 45
Steering Adjustments on 1950 Cars	Dec. 42

BODY SERVICE AND PAINTING

Appearance Reconditioning	Feb. 56
Be a Body Beautician	April 46
Modern Paint Department Meets Competition	April 56
When It Rains It Leaks	June 42
Sell 'Em When You See 'Em	July 42
How to Install Repair Panels	Aug. 44
Know Your Polishes, Waxes and Cleaners	Sept. 42
Fisher Body Windshield Glass Replacement	Sept. 48
"Out, Out Damned Spot"	Oct. 44
Paint Number Locations on 1950 Cars	Oct. 57
Guarantee a Good Paint Job	Nov. 50
Aligning Buick Hoods	Dec. 48

TUNE UP

Pop Makes a Popper Purr	Jan. 60
Servicing the Carter Mechanical Fuel Pump	Feb. 52
Servicing the Rochester Chevrolet Carburetor	Mar. 40
Pop Clears the Track	June 46
Overhauling the Auto-Lite Fuel Pump	Oct. 72
Tommy Screws Things Up	Nov. 46
Chemicals Save Shop Time	Dec. 54
Flexible Fuel Lines	Dec. 51

ELECTRICAL AND IGNITION SERVICE


Larry Uses His Head	Feb. 46
Tommy Shows Resistance to Pop	Mar. 44
Modern Equipment Makes Quick Checks	June 44
Pop Tows in a Customer	Aug. 42
Neglected Wires Cause Fires	Oct. 50

MECHANICS' TRAINING

Pop Makes & Popper Purr	Jan. 60
Hydraulic Valve Lifters	Jan. 62
Service Highlights on the 1950 Cars	Jan. 78
Trouble Shooting on the Dynaflo (Part 1)	Feb. 40
Larry Uses His Head	Feb. 46
We Need Trained Mechanics	Feb. 48
Servicing the Carter Mechanical Fuel Pump	Feb. 52
Appearance Reconditioning	Feb. 56
Here's How to Install Overdrive on Plymouth	Feb. 59
Servicing the Rochester Chevrolet Carburetor	Mar. 40
Tommy Shows Resistance to Pop	Mar. 40
Sun's Training Program for Servicemen	Mar. 48
Shop Lathes	Mar. 55
Trouble Shooting on the Dynaflo (Part 2)	Mar. 58
Finding Trouble on Faulty Brake Systems	Apr. 42
Pop Gets the Drop on a Drip	Apr. 44
Trouble Shooting on the Dynaflo (Part 3)	Apr. 60
Trouble Shooting on Differentials	May 42
Pop Whips A Whine	May 44
Servicing the Fluid Drive Unit	May 53
When it Rains It Leaks	June 42
Modern Equipment Makes Quick Checks	June 44
Pop Clears the Track	June 46
Causes of Cooling Complaints	June 53
Dropping the Pans on 1950 Cars	July 40
Pop Hits the Line	July 44
Small Engines Need Repairs, Too	July 46
How to Use a Micrometer	July 50
Overhauling the Crosley Engine	July 54
Servicing the 1950 Studebaker Automatic Transmission	Aug. 38
Tips on Valve Jobs	Aug. 40
Pop Tows in a Customer	Aug. 42
How to Install Repair Panels	Aug. 44
Adjusting Brakes on Current Models	Aug. 50
Servicing the Nash Rambler Front End	Sept. 44
Pop Quiets a Knocker	Sept. 46
Fisher Body Windshield Glass Replacement	Sept. 48
"Out, Out Damned Spot"	Oct. 44
Pop Springs a Surprise	Oct. 46
Cleaning and Recoring Radiators	Oct. 48
Overhauling the Auto-Lite Fuel Pump	Oct. 72
Quick Oil Pressure Tests on Powerglide	Nov. 44
Spring Suspension Service	Nov. 45
Tommy Screws Things Up	Nov. 46
How Much Oil Should a Car Use?	Nov. 48
Guarantee a Good Paint Job	Nov. 50
Steering Adjustments on 1950 Cars	Dec. 42
Aligning Buick Hoods	Dec. 48
Adjusting the Chevrolet Vacuum Shift	Dec. 50
The Killer That Can Be Stopped	Dec. 41

ENGINE THEORY AND MAINTENANCE

Hydraulic Valve Lifters	Jan. 62
Pop Gets the Drop on a Drip	Apr. 44
Causes of Cooling Complaints	June 53
Dropping the Pans on 1950 Cars	July 40



FEATURE ARTICLES ON—BRAKES • TUNE-UP • TRANSMISSIONS



MECHANICAL FEATURES

STEERING AND SUSPENSION

	Page
Sell Shock Absorber Service	April 55
Servicing the Nash Rambler Front End	Sept. 44
New Life for Dead Shocks	Oct. 52
Spring Suspension Service	Nov. 45
Steering Adjustments on 1950 Cars	Dec. 42

BODY SERVICE AND PAINTING

Appearance Reconditioning	Feb. 56
Be a Body Beautician	April 46
Modern Paint Department Meets Competition	April 56
When It Rains It Leaks	June 42
Sell 'Em When You See 'Em	July 42
How to Install Repair Panels	Aug. 44
Know Your Polishes, Waxes and Cleaners	Sept. 42
Fisher Body Windshield Glass Replacement	Sept. 48
"Out, Out Damned Spot"	Oct. 44
Paint Number Locations on 1950 Cars	Oct. 57
Guarantee a Good Paint Job	Nov. 50
Aligning Buick Hoods	Dec. 48

TUNE UP

Pop Makes a Popper Purr	Jan. 60
Servicing the Carter Mechanical Fuel Pump	Feb. 52
Servicing the Rochester Chevrolet Carburetor	Mar. 40
Pop Clears the Track	June 46
Overhauling the Auto-Lite Fuel Pump	Oct. 72
Tommy Screws Things Up	Nov. 46
Chemicals Save Shop Time	Dec. 54
Flexible Fuel Lines	Dec. 51

ELECTRICAL AND IGNITION SERVICE


	Page
Larry Uses His Head	Feb. 46
Tommy Shows Resistance to Pop	Mar. 44
Modern Equipment Makes Quick Checks	June 44
Pop Tows in a Customer	Aug. 42
Neglected Wires Cause Fires	Oct. 50

MECHANICS' TRAINING

Pop Makes & Popper Purr	Jan. 60
Hydraulic Valve Lifters	Jan. 62
Service Highlights on the 1950 Cars	Jan. 78
Trouble Shooting on the Dynaflo (Part 1)	Feb. 40
Larry Uses His Head	Feb. 46
We Need Trained Mechanics	Feb. 48
Servicing the Carter Mechanical Fuel Pump	Feb. 52
Appearance Reconditioning	Feb. 56
Here's How to Install Overdrive on Plymouth	Feb. 59
Servicing the Rochester Chevrolet Carburetor	Mar. 40
Tommy Shows Resistance to Pop	Mar. 40
Sun's Training Program for Servicemen	Mar. 48
Shop Lathes	Mar. 55
Trouble Shooting on the Dynaflo (Part 2)	Mar. 58
Finding Trouble on Faulty Brake Systems	Apr. 42
Pop Gets the Drop on a Drip	Apr. 44
Trouble Shooting on the Dynaflo (Part 3)	Apr. 60
Trouble Shooting on Differentials	May 42
Pop Whips A Whine	May 44
Servicing the Fluid Drive Unit	May 53
When it Rains It Leaks	June 42
Modern Equipment Makes Quick Checks	June 44
Pop Clears the Track	June 46
Causes of Cooling Complaints	June 53
Dropping the Pans on 1950 Cars	July 40
Pop Hits the Line	July 44
Small Engines Need Repairs, Too	July 46
How to Use a Micrometer	July 50
Overhauling the Crosley Engine	July 54
Servicing the 1950 Studebaker Automatic Transmission	Aug. 38
Tips on Valve Jobs	Aug. 40
Pop Tows in a Customer	Aug. 42
How to Install Repair Panels	Aug. 44
Adjusting Brakes on Current Models	Aug. 50
Servicing the Nash Rambler Front End	Sept. 44
Pop Quiets a Knocker	Sept. 46
Fisher Body Windshield Glass Replacement	Sept. 48
"Out, Out Damned Spot"	Oct. 44
Pop Springs a Surprise	Oct. 46
Cleaning and Recoring Radiators	Oct. 48
Overhauling the Auto-Lite Fuel Pump	Oct. 72
Quick Oil Pressure Tests on Powerglide	Nov. 44
Spring Suspension Service	Nov. 45
Tommy Screws Things Up	Nov. 46
How Much Oil Should a Car Use?	Nov. 48
Guarantee a Good Paint Job	Nov. 50
Steering Adjustments on 1950 Cars	Dec. 42
Aligning Buick Hoods	Dec. 48
Adjusting the Chevrolet Vacuum Shift	Dec. 50
The Killer That Can Be Stopped	Dec. 41

ENGINE THEORY AND MAINTENANCE

Hydraulic Valve Lifters	Jan. 62
Pop Gets the Drop on a Drip	Apr. 44
Causes of Cooling Complaints	June 53
Dropping the Pans on 1950 Cars	July 40



WHEEL ALIGNMENT • BODY REPAIRS • ELECTRICAL SERVICE

	Page
Small Engines Need Repairs, Too	July 46
Overhauling the Crosley Engine	July 54
Tips on Valve Jobs	Aug. 40
How Much Oil Should a Car Use?	Nov. 48

COOLING SYSTEM

Causes of Cooling Complaints	June 53
Cleaning and Recoring Radiators	Oct. 48

POWER TRAIN MAINTENANCE

Trouble Shooting on the Dynaflo (Part 1) ...	Feb. 40
Here's How to Install Overdrive on Plymouth ..	Feb. 59
Trouble Shooting on the Dynaflo (Part 2)....	Mar. 58
Trouble Shooting on the Dynaflo (Part 3) ...	Apr. 60
Pop Whips a Whine	May 44
Trouble Shooting on Differentials	May 42
Servicing the Fluid Drive Unit	May 53
Servicing the 1950 Studebaker Automatic Transmission	Aug. 38
Pop Quiets a Knocker	Sept. 46
Quick Oil Pressure Tests on Powerglide	Nov. 44
Adjusting the Chevrolet Vacuum Shift	Dec. 50

BRAKE SERVICE

Finding Trouble on Faulty Brake Systems	Apr. 42
Pop Hits the Line	July 44
Adjusting Brakes on Current Models	Aug. 50

NEWS AND EDITORIAL FEATURES

SPECIAL EDITORIAL FEATURES

	Page
"A Blonde That Can Cook"	Feb. 38
We Need Trained Mechanics	Feb. 48
May is Car Safety Month	Apr. 38
Parsons Wins	June 40
Five Million Owners Can't Be Wrong	Sept. 40
Opportunity of a Lifetime	Oct. 41
Neglected Wires Cause Fires	Oct. 50
How to Win Sales and Influence Customers ...	Nov. 52

NEW CARS AND TRUCKS

1950 Nash	Jan. 38
1950 Chevrolet	Jan. 39
1950 Dodge	Jan. 40
1950 Buick	Jan. 41
1950 Plymouth	Jan. 42
1950 Oldsmobile	Jan. 43
1950 DeSoto	Jan. 44
1950 Chrysler	Jan. 45
Hudson Completes Line for 1950	Feb. 44
The 1950 Cadillac	Feb. 45
Kaiser Adds Low-Priced Model to 1951 K-F Line	Mar. 38
Willys Announces the New F-Head Engine	Apr. 41
Nash Announces New Light Car	May 50
1951 Packard Offers New Body	Sept. 38
1951 Nash Offers Many Improvements	Oct. 38
Hudson Adds the "Hornet"	Nov. 39
Studebaker Introduces V-8 Engine	Nov. 40
Lincoln and Mercury Announce 1951 Lines	Nov. 42
1951 Chevrolet	Dec. 39

	Page
Ford Restyles for 1951	Dec. 40
Pontiac Changes for 1951	Dec. 38

NEW DEVELOPMENTS

Ford Automatic Transmission	Jan. 66
Chevrolet Automatic Transmission	Jan. 76
Studebaker Automatic Transmission	Jan. 68
Willys Announces the New F-Head Engine	Apr. 41
Supercharged Offenhauser	May 40
The Mercury-Ford Automatic Transmission ..	June 48
Removing Carbon Without Removing the Head ..	Aug. 46
Studebaker Introduces the V-8 Engine	Nov. 40
Chemicals Save Shop Time	Dec. 54

GENERAL INTEREST

Service Highlights on the 1950 Cars	Jan. 78
Highlights of the Hot Rod Show	Mar. 42
Mercury Wins Sweepstakes in Grand Canyon Run	Mar. 46
Parsons Wins	June 40
Repairman Builds Midget Tractor Unit	Aug. 49
Five Million Owners Can't Be Wrong	Sept. 40
Know Your Polishes, Waxes and Cleaners ...	Sept. 42

MANAGEMENT FEATURES

BUSINESS PROCEDURES

Pump the Water Out of Your Business	Jan. 64
Motor Age Business Guide for 1950	Jan. 69
Price Your Jobs for Profits	Feb. 50
Two Methods of Profit Sharing	Mar. 56
Don't Give Your Profits Away!	Apr. 48
Watch Out for the Gremlins in Costing	May 48
What Do You Know About Managing Your Business?	June 50
Cutting Costs	June 56
Keep Enough Money in the Till	July 48
Don't Let Depreciation Mean "Dead Loss" ...	Sept. 52

SALES AND ADVERTISING

Merchandising Methods	Jan. 58
Sales Analysis of New Car Business for 1950 ..	Jan. 76
Appearance Reconditioning	Feb. 56
Be a Body Beautician	Apr. 46
Sell Shock Absorber Safety Service	Apr. 55
The Secret of Selling Seat Covers	Apr. 64
This Summer Sell Safety	May 46
Pay Dirt!	June 52
Sell 'Em When You See 'Em	July 42
Sell Used Cars Today	July 51
Formula for Success	Aug. 48
We Increased Service Volume 300 Per Cent. ...	Sept. 51
Opportunity of a Lifetime	Oct. 41
How to Win Sales and Influence Customers ...	Nov. 52
The Killer That Can Be Stopped	Dec. 41
How to Handle Flexible Fuel Lines	Dec. 51

SHOPS AND DEALERSHIPS

Two Methods of Profit Sharing	Feb. 55
Why Midway Makes Money	May 52
Cutting Costs	June 56
Formula for Success	Aug. 48
We Increased Service Volume 300 Per Cent. ...	Sept. 51
Operating for Success	Dec. 55